

DETAILS OF WORKS / CONSULTANCY / PURCHASE CONTRACTS AWARDED ON NOMINATION BASIS

3RD QUARTER OF 2017 - 18 (OCT 2017 - DEC 2017)

DETAILS OF PURCHASE CONTRACT

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
SR. NO	Name of Work/Description of Item	Tender/Quotation No. & Date	Name of Agency	P.O. No. & Date	Purchase Order Value (Rs. in Lakhs)	Contract Period	Reasons for Nomination	Approving Authority	UNIT
1	Supply of Gents Leather Shoes	Tender No. CMM/MISC/00-78-5-4135 dtd. 11/08/2017 Quotation No. Nil dtd. 11/09/2017	M/s. M&B Footwear Pvt. Ltd., (Corporate Office) C-33, Sector - 58, Noida - 201 301, UP (INDIA)	CMM/MISC/00-78-5-4135/PO/20068 Dated : 06-12-2017	26.62	16-03-2018	As per approval of ED(HR) in line with Circular Issued by GM(HRP) Lr.No.NPCIL/HQ/HRP/11(101)/2014/739 Dtd.22.12.14 and Lr.No.NPCIL/HQ/HRP12(7)/2016/327 Dtd.29.09.2016 and being an ER issue.	AD(HR)	Misc. Group C&MM-HQ
2	National Safety Calendar	I/22027	M/S NATIONAL SAFETY COUNCIL,MUMBAI	29768 DTD. 12-12-2017	0.41	27-01-2018	NSC CALENDAR	CS, NAPS	NAPS
3	National Safety Diary-2018	I/22028	M/S NATIONAL SAFETY COUNCIL,MUMBAI	29774 DTD. 16-12-2017	0.41	03-01-2018	NSC DIARY	TSS, NAPS	NAPS
4	JINDAL MAKE 50 NB 160 Sch PIPE, SA333 Gr.6, ANSI B36.10, (SOR Item No. 1.2.10) (36 MTR)	Tender No. KAPP-3&4/CAP/C&MM/1670 and Quotation no. NIL dtd 16-10-2017.	M/S.A 1 SALES CORPORATION Mumbai-400 009.	CMM/MMW/KAPP-3&4/CAP/2541/CAP/PO-1670 DTD. 22-11-2017	0.97	14-12-2017	Pipe required urgently for completion of PHT circuit no.4 which is on critical path of project schedule for K#3.	ACE (NP&CS), KAPP-3&4	Kakrapar Gujarat Site
5	Supply of Thordon bearing for use in Fire water Jockey pump intermediate shaft, Size ID:42.77, OD:50 (6 No.)	Tender No. KAPP-3&4/CAP/C&MM/1670 and Quotation no. SEPL/586/AS/RP/RM/17-18/560 dtd.22-11-2017	M/S.SONEJI ENGINEERING PVT.LTD Plot No.B/6 & B/7, Global Industrial Park, Survey No.26/2, Near Nauli Railway Crossing, Village-Valvada, Dist.Valsad. Vapi-396 105	CMM/MMW/KAPP-3&4/CAP/2573/CAP/PO-1677 DTD. 27-11-2017	0.47	09-12-2017	Fire water jockey pump was found not developing pressure during test run due to shaft sheared at fifth intermediate shaft from the top & line bearing were damaged and needed to be replaced to resume operation of the pump, so pump to be restored at earliest for making available SUT fire protection.	MS, KAPP-3&4	Kakrapar Gujarat Site